220-701 CompTIA A+ Essentials (2009) Exam

Number: EnsurePass Passing Score: 700 Time Limit: 90 min File Version: 13.02



http://www.gratisexam.com/



Vendor: CompTIA Exam Code: 220-701

Exam Name: CompTIA A+ Essentials (2009)

Version: 13.01

Contact us:

If you have any suggestions or any questions about our product, please feel free to contact us: support@ensurepass.com

About Products:

Free update is available within 180 days after your purchase.

Please login your user center and download the latest product anytime.

PS:Ensure you can pass the exam, please check the latest product in 2-3 days before the exam again.

Copyright @2006-2013 EnsurePass.com, All right reserved.

Exam A

QUESTION 1

When servicing a laptop, which of the following components usually requires the keyboard to be removed before the component can be replaced?

- A. Processor
- B. Hard drive
- C. Battery
- D. Optical drive

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 2

When adding a FireWire adapter to a laptop, which of the following ports would MOST likely be used?

- A. MMC port
- B. SODIMM slot
- C. Express card 34
- D. USB 1.1 port

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 3

Which of the following expansion cards would MOST likely require the use of an external power connector to function properly?

- A. PCI Express video card
- B. PCI Express fiber card
- C. PCI Express sound card
- D. PCI Express network card

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 4

RG-59 is a designation for which of the following cable types?

- A. Plenum
- B. Fiber optic
- C. Twisted pair

D. Coaxial

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Which of the following wireless standards has a transfer speed of 11 Mbps?

- A. 802.11a
- B. 802.11b
- C. 802.11g
- D. 802.11n

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Which of the following is the only place where initial boot settings can be configured?

- A. CMOS
- B. BIOS
- C. MBR
- D. HAL

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 7

A user reports that their thermal wristband printer is printing barcodes that will not scan properly. Which of the following maintenance techniques would MOST likely resolve this issue?

- A. Replace the print roller
- B. Reset to factory defaults
- C. Replace the wristband roll
- D. Clean the heating assembly

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 8

A user is experiencing headaches and motion sickness symptoms when using their new computer monitor. Which of the following can a technician adjust to help the user?

- A. Privacy filter
- B. Refresh rate
- C. Use a digital signal
- D. Brightness

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following is MOST likely a managed, Layer 3 device?



http://www.gratisexam.com/

- A. Router
- B. Bridge
- C. Hub
- D. Switch

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 10

A computer's case fan protects against which of the following environmental concerns?

- A. Pressure
- B. Heat
- C. Brown out
- D. Cold

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Which of the following is the number of octets in an IPv4 address?

- A. 4
- B. 8
- C. 16
- D. 64

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 12

Which of the following is enabled in the BIOS that will prompt a user to enter their password every time the laptop performs a POST?

- A. Power User access
- B. Power on password
- C. Administrative password
- D. User profile access

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Which of the following expansion slots would be MOST likely used to install an additional NIC into a desktop PC?

- A. PCI
- B. AGP 8x
- C. Mini PCI
- D. PCI Express x16

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 14

Which of the following RAM types is used if it is labeled as 4 GB PC1333?

- A. RAMBUS
- B. DDR3
- C. SDIMM
- D. SIM

Correct Answer: B Section: (none)

Explanation

Explanation/Reference:

QUESTION 15

Which of the following is the IPv6 loopback address?

- A. ::1
- B. 1.1.1.1
- C. 127.0.0.1
- D. 255,255,254

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 16

The memory slots that are not populated with RAMBUS memory modules require which of the following devices?

- A. RIMM
- B. CRIMM
- C. SODIMM
- D. DIMM

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 17

A technician replacing a CRT monitor and the battery inside of a UPS wishes to dispose of the replaced hardware. Which of the following should the technician do to BEST ensure proper disposal?

- A. Store equipment in IT inventory.
- B. Donate to a local nonprofit organization.
- C. Follow local government regulations for disposal.
- D. Affix MSDS sheet to items for the waste management company.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 18

Which of the following are MOST important when building a home server PC? (Select THREE).

A. HDMI output

- B. Media streaming
- C. TV tuner
- D. Dual monitors
- E. File sharing
- F. High-end video card
- G. Print sharing

Correct Answer: BEG Section: (none) Explanation

Explanation/Reference:

QUESTION 19

Which of the following components is MOST important when building a Gaming PC?

- A. File sharing
- B. TV tuner
- C. Media streaming
- D. High-end video card

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 20

Which of the following computers are used for basic applications and meets the MINIMUM requirements for running Windows?

- A. Virtualization workstation
- B. Home server PC
- C. CAD workstation
- D. Thin client

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 21

The BIOS settings on a gaming laptop shows the current CPU speed at 3.5GHz. The default speed specification of the CPU is 3.2 GHz with FSB at 800 MHz and locked CPU multiplier at 4x. Which of the following speed settings needs to be changed in the BIOS in order to run the CPU on its default frequency?

- A. RAM CAS latency
- B. FSB
- C. FSB to CPU ratio
- D. Multiplier

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 22

Which of the following should be avoided when installing a laser printer?

- A. Surge protector
- B. UPS
- C. RJ-45 connector
- D. Toner

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 23

A PC cannot connect to the network. A network card was purchased without documentation or driver discs. Which of the following is the BEST way to install it into this machine?

- A. Download and install the drivers
- B. Run Windows update to install drivers
- C. Copy drivers to flash drive and install
- D. Purchase the disc online and install

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 24

A coworker has reported that someone has engaged in prohibited activity. The supervisor has asked the technician to quarantine the PC until police arrive. Which of the following should the technician do? (Select TWO).

- A. Allow the user to continue working
- B. Check for viruses
- C. Re-image the hard drive
- D. Document time/date for later reference
- E. Prevent users from accessing the PC
- F. Turn off PC

Correct Answer: DE Section: (none) Explanation

Explanation/Reference:

QUESTION 25

Which of the following cables would use a DB-15 connector type?

- A. HDMI
- B. Optical
- C. VGA
- D. DVI

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 26

When configuring a POS system, which of the following peripheral devices would MOST likely need to be installed? (Select THREE).

- A. Optical mouse
- B. Handheld digitizer
- C. Barcode reader
- D. Touchscreen
- E. Document scanner
- F. Keyboard
- G. External USB drive

Correct Answer: BCD Section: (none) Explanation

Explanation/Reference:

QUESTION 27

Which of the following is the subnet mask for a Class C IP address?

- A. 10.0.0.1
- B. 192.168.1.1
- C. 255.255.0.0
- D. 255.255.255.0

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 28

A customer needs to run 3 virtual machines on their software design workstation. Which of the following CPUs would be MOST cost effective for this task?

- A. 3 Core
- B. 4 Core
- C. 8 Core
- D. 12 Core

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 29

Which of the following protocols is used by thin clients?

- A. IPX
- B. NetBIOS
- C. RDP
- D. UDP

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 30

Which of the following represents a wiring standard for twisted pair cables?

- A. Fiber
- B. T568A
- C. IEEE1394
- D. CAT5

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 31

A customer has asked for the ability to operate dual digital monitors. Which of the following is the BEST solution for accomplishing this?

- A. Split the onboard video port.
- B. Update the video drivers to allow for multiple monitors.
- C. Add an adaptor to the onboard VGA port.
- D. Install a video card with multiple DVI ports.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 32

Which of the following memory types is unique in that it generates so much heat it requires that the memory modules are covered in heat sinks?

- A. RAMBUS
- B. DDR3
- C. DDR
- D. SDRAM

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 33

Which of the following is an example of a Class B TCP/IP address?

- A. 4.4.4.2
- B. 122.29.38.110
- C. 155.43.29.219
- D. 199.200.201.202

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 34

A user is trying to use Remote Desktop to connect to another computer on the LAN. The connection fails. The technician opens up a command prompt and types the following: "telnet computernamE. 3389" and also gets the same error message. Which of the following is the MOST likely cause of this error, assuming that the OS firewall has been disabled?

- A. The antivirus software is blocking the incoming connection.
- B. The ISP is blocking Remote Desktop at their end.
- C. The RDP connection has been configured to use a non-standard port.
- D. The telnet service has not been installed.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 35

Which of the following is the correct arrangement of the data pairs in a T568B wire pattern? (Select TWO).

A. Orange & orange/white on pins 1 & 2

- B. Blue & blue/white on pins 4 & 5
- C. Orange & orange/white on pins 4 & 5
- D. Brown & brown/white on pins 1 & 2
- E. Green & green/white on pins 3 & 6

Correct Answer: AE Section: (none) Explanation

Explanation/Reference:

QUESTION 36

Which of the following would be included when documenting the MOST recent policy on corporate behavior?

- A. Page numbers
- B. Author of the document
- C. A complete table of contents
- D. Last revision dates and version numbers

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 37

Which of the following would a user MOST need for a home theater PC? (Select TWO).

- A. Liquid cooling
- B. Network card
- C. TV tuner card
- D. CPU
- E. RAM
- F. Specialized audio card

Correct Answer: CF Section: (none) Explanation

Explanation/Reference:

QUESTION 38

Which of the following can be installed to avoid brown outs?

- A. A larger electrical breaker
- B. An inline fuse box
- C. A UPS
- D. Multiple power supplies

Correct Answer: C Section: (none)

Explanation

Explanation/Reference:

QUESTION 39

Which of the following should be documented when transferring ownership of a PC suspected of prohibited activity? (Select TWO).

- A. List of prohibited content
- B. Date
- C. Age
- D. Prohibited activity
- E. Name of receiving party

Correct Answer: BE Section: (none) Explanation

Explanation/Reference:

QUESTION 40

When comparing analog display inputs to digital display inputs, which of the following is an advantage that digital has over analog?

- A. Allows for higher brightness
- B. More crosstalk
- C. Sustains higher resolutions
- D. Supports widescreen resolutions

Correct Answer: C Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/

QUESTION 41

Which of the following network topologies is MOST likely to affect other devices on the network if there is a problem with one of the devices?

- A. Mesh
- B. Bus
- C. Ring
- D. Star

Correct Answer: C

Section:	(none)
Explanat	ion

Explanation/Reference:

QUESTION 42

Which of the following pin pairs remain with the same wire color for either T568A or T568B?

- A. Pair 1 & 8
- B. Pair 2 & 7
- C. Pair 3 & 6
- D. Pair 4 & 5

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 43

Which of the following Internet connection types would have the MOST available bandwidth and highest transmission speed?

- A. DSL
- B. Dial-up
- C. Cable
- D. Satellite

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 44

Which of the following BIOS settings is MOST likely to speed up the boot process when disabled?

- A. IDE Auto Detect
- B. BIOS Administrator Password
- C. Advanced Configuration and Power Interface
- D. Plug and Play

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 45

A user is present when a technician is troubleshooting their workstation. They insist on showing the technician, step by step, what occurred. How should the technician deal with this situation?

- A. Allow the user to demonstrate expertise.
- B. Do not argue; empathize with the user, and offer to help.
- C. Ask the user to watch as the technician diagnoses and corrects the problem.
- D. Document each of the steps to replicate at a later time.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 46

Which of the following network topologies is characterized by a central server and unique connections to all clients?

- A. Star
- B. Bus
- C. Mesh
- D. Ring

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 47

Which of the following would be an example of prohibited content?

- A. Third party proxy sites
- B. Malicious cookie
- C. Detected virus
- D. Unwanted pop-up

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 48

A technician is dispatched to a location. While working, the technician's cell phone rings. Which of the following actions should the technician take?

- A. Answer the call to determine its importance.
- B. Ignore the call and return the call from a land line.
- C. Answer the call and leave the location in order to talk.
- D. Silence the phone and allow the call to go to voice mail.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 49

A home user would like to connect their laptop display to their home HD television. Which of the following is the BEST solution?

- A. Connecting the laptop's VGA output to an HDMI adaptor
- B. Connecting the laptop's VGA output to the television's VGA input
- C. Connecting the laptop's USB output to the HD television's HDMI adaptor
- D. Connecting the laptop's USB output to the television's USB input

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 50

A technician has been asked to ensure a PC is supplied with power for a short time, during a power failure. The technician should install which of the following devices to ensure this requirement is easily met?

- A. Backup power generator
- B. Uninterruptable power supply
- C. Power line conditioners
- D. Surge protectors

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 51

A technician is dispatched to install additional RAM in a computer. The technician unplugs the system from the power source, and removes the cover of the PC. Which of the following should the technician do NEXT?

- A. Update the BIOS for compatibility.
- B. Put on an ESD strap.
- C. Use an anti-static bag to hold the RAM while installing.
- D. Clean out the PC with compressed air.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 52

When comparing DSL broadband to cable broadband, which of the following is an advantage of DSL broadband?

- A. Upgraded copper lines allow maximum speed greater than cable
- B. Signal is not shared back to the switch
- C. Signal is shared back to the switch
- D. Distance is not a factor in signal speed

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 53

After swapping an internal wireless card on a laptop with an identical model, the technician notices that the wireless does not work. Which of the following would be the MOST likely cause?

- A. Antennae is not connected
- B. Wireless card is defective
- C. Drivers needs to be updated
- D. OS needs to be updated

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 54

Which of the following is the correct configuration for a RAID 5 array?

- A. A two disk set with one data strip
- B. A three disk set with two data strips and a parity strip
- C. A two disk set with two data strips
- D. A four disk set with two sets of data strips

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 55

A user has a new laptop with a quad-core processor, and wants to increase the memory of the unit. Which of the following memory types would be the BEST choice?

- A. DIMM
- B. RIMM
- C. SIMM
- D. SODIMM

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 56

Which of the following network types is being described when computers are connected so that data flows from one computer to the other by traveling through each computer in the network?

- A. Star
- B. Hybrid
- C. Mesh
- D. Ring

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 57

After a technician replaces a laptop display, the technician now notices that the wireless no longer works. Which of the following would be the MOST likely cause?

- A. The wireless switch was damaged during the display installation.
- B. The network card has failed.
- C. The new display is interfering with the wireless signal.
- D. The antenna connector was not reconnected.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 58

After making a long CAT5 cable, the technician fears that the cable may have been damaged during the pull, but does not have a cable tester. Which of the following would be the BEST alternative tool to determine whether there are any breaks or shorts in the cable?

- A. Multimeter
- B. Voltmeter
- C. Loopback plug
- D. Toner probe

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 59

Which of the following connector types does CAT5e require to connect it from a PC to a switch or router?

- A. RJ-45
- B. RJ-11
- C. BNC
- D. LC

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 60

Which of the following is the form factor of a standard S-video connector?

- A. DB-15
- B. DB-25
- C. DIN-6
- D. DB-9

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 61

Which of the following are standard AMD processor socket types? (Select TWO).

- A. 1366
- B. 1155
- C. 940
- D. LGA
- E. F

Correct Answer: CE Section: (none) Explanation

Explanation/Reference:

QUESTION 62

Which of the following is the MOST critical component related to removing heat from the CPU?

- A. Vented case
- B. Number of fans
- C. Thermal paste
- D. Liquid cooling

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 63

Which of the following is the form factor of a standard VGA connector?

- A. DB-15
- B. DB-9
- C. DIN-6
- D. DB-25

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 64

When computers are connected on a network in a manner where the data flows to a central point and then back out describes which of the following networks?

- A. Ring
- B. Mesh
- C. Star
- D. Hybrid

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 65

A technician is going to install a gigabit Ethernet adapter into a laptop for a customer. Which of the following technologies is MOST likely being used in this installation?

- A. Express card 54
- B. USB 2.0
- C. PCle
- D. Port replicator

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 66

A basic cable tester can be used to do which of the following?

- A. Assure end to end continuity of a UTP cable.
- B. Locate the distance to a cable break.

- C. Determine the CAT level of a UTP cable.
- D. Determine the distance to the nearest wiring closet.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 67

A laptop typically has a physical switch to disable which of the following features?

- A. Bluetooth
- B. Hard Drive Impact Protection
- C. Data Encryption
- D. Wireless

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 68

A technician is told to make 50 foot (15.24 meters) patch cables, and is given a spool of CAT6 UTP cable and a bag of RG-45 connectors. Which of the following tools would BEST be used to do this task? (Select TWO).

- A. A cable tester
- B. A crimper
- C. A cable wiring chart
- D. A toner probe
- E. A multimeter
- F. A cutting shear

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 69

A technician needs to find an end of a network cable drop. Which of the following tools would the technician use?

- A. Cable
 - tester
- B. Multimeter
- C. Toner probe
- D. Loopback plug

Correct Answer: C

Section: (none) Explanation

Explanation/Reference:

QUESTION 70

A company would like to create and maintain a web presence by operating a web server and an FTP server for users to upload and download job specifications. Which of the following Internet connection types would be BEST suited for this type of traffic?

- A. Satellite
- B. Fiber
- C. 4G mobile hotspot
- D. DSL

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 71

User 1 has a printer connected to a PC. User 2 is requesting the ability to print large documents to that printer. Which of the following is the BEST way for User 2 to gain access to the printer?

- A. Use infrared to print remotely.
- B. Unplug the printer and install it on the new PC.
- C. Share the Printer in Windows.
- D. Update universal drivers to allow printing.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 72

Which of the following ISP types requires an RJ-11 connection to the PC?

- A. Cellular
- B. Cable
- C. Dial-up
- D. WiMAX

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 73

Which of the following connection types are MOST likely to be found in the front of a PC case? (Select TWO).

- A. Molex
- B. RS-232
- C. SATA
- D. USB
- E. Audio

Correct Answer: DE Section: (none) Explanation

Explanation/Reference:

QUESTION 74

The network printer is locking up and printing garbled text. When the user cancels the job from their local print queue, nothing happens. Which of the following is the MOST likely cause?

- A. The printer needs to be power cycled to clear the job.
- B. The print server's queue needs to be checked.
- C. The printer needs to be set to factory defaults.
- D. The user's workstation needs to be rebooted.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 75

Which of the following cable types can transmit at 100 Mbps and has the SAME transmission distance without the use of a repeater? (Select TWO).

- A. CAT6
- B. RG-59
- C. CAT5e
- D. CAT3
- E. RG-6

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 76

A user is trying to connect a mobile IR printer to a mobile device with no success. Which of the following is the MOST important when printing to an IR printer?

- A. Enough light
- B. Line of sight
- C. Correct printer drivers
- D. Enough power

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 77

The security team has implemented new guidelines on how to handle sensitive information stored on workstations based on a past incident involving information found on donated workstations. Which of the following should be completed by technicians before donating the workstations?

- A. Install a new operating system
- B. Delete users' data before donation
- C. Write the drive with 1's and 0's three times
- D. Delete all partitions of the hard drive

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 78

Which of the following could be the number of cores contained within AMD processors that utilize AM3 socket? (Select TWO).

- A. 4
- B. 5
- C. 6
- D. 7
- E. 12

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 79

Which of the following technologies is responsible for communication with the CPU?

- A. eSATA
- B. PCI express
- C. Southbridge
- D. Northbridge

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 80

Which of the following display types is likely to draw the LEAST amount of power?

- A. LCD
- B. LED
- C. CRT
- D. Plasma

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 81

Which of the following settings is MOST likely to be controlled through the use of a laptop's Function (Fn) key? (Select TWO).

- A. Wireless
- B. Brightness
- C. Sleep Mode
- D. NumPad
- E. Power

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 82

A user reports that the laser printer is constantly jamming on humid days. Which of the following is the MOST likely resolution to the problem?

- A. Replace the paper with thinner paper.
- B. Replace the toner cartridges.
- C. Replace the fuser.
- D. Replace the print heads.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 83

A technician has installed a new motherboard in a workstation, but after hardware tests, the motherboard has failed. Which of the following should the technician do FIRST before replacing the motherboard?

- A. Reseat all power connections.
- B. Remove the CMOS battery.

- C. Install the graphics card.
- D. Ground to the case.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 84

A user would like to ensure that only their family and their laptops can access a newly installed wireless router. Which of the following BEST accomplishes this?

- A. MAC filtering
- B. Disable DHCP
- C. Static IP addresses
- D. Port forwarding

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 85

A user is printing pictures to the color laser printer and the bottom half of the picture is faded. The printer is displaying no errors. Which of the following is the MOST likely resolution to the problem?

- A. Replace the printer ribbon.
- B. Replace the pickup assembly.
- C. Replace the fuser.
- D. Replace the print head.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 86

Which of the following wireless technologies is primarily setup for video/audio and the frequency is 5 GHz?

- A. Cellular
- B. 802.11a
- C. 802.11b
- D. Satellite

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 87

Which of the following is best practice when installing memory into a computer?

- A. Install memory modules in pairs.
- B. Insure the proper drivers are installed for best performance.
- C. Apply thermal grease to insure proper seating.
- D. Wear an anti-static wrist strap.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 88

Which of the following is correct about differences in CAT5 and CAT6 connectors?

- A. CAT5 connectors have locking tabs
- B. CAT5 and CAT6 use the same connectors
- C. CAT6 supports three different wiring standards
- D. CAT6 connectors are longer for better contact

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 89

Which of the following network cable types is MOST often used in environments where physical security of the data is the top priority?

- A. UTP
- B. Coaxial
- C. Fiber optic
- D. STP

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 90

Which of the following wireless networking standards can operate at two different frequencies simultaneously?

- A. 802.11a
- B. 802.11b
- C. 802.11g
- D. 802.11n

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 91

A laptop will not output to a connected projector. Which of the following steps should a technician take FIRST?

- A. Press the appropriate function + monitor key.
- B. Adjust the BIOS settings for external display.
- C. Replace the video card on the laptop.
- D. Update video drivers for the video card.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 92

Which of the following would a technician MOST likely consider to avoid electrical shock with a decommissioned CRT?

- A. Degaussing the monitor.
- B. Destroying the tube.
- C. Removing the plastic housing.
- D. Disposing at a recycling center.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 93

A user cannot undock a laptop from the docking station. Which of the following is the MOST likely cause?

- A. The laptop is not turned off
- B. The power cable is not unplugged
- C. The lock button is set to lock
- D. The ACPI settings are configured improperly

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 94

A customer calls in, talking constantly without allowing time for the technician to answer or ask questions. The

technician decides to place the customer on hold to work on another issue and misses what the customer's problem was. When the customer is finished explaining the issue, the technician asks the customer to summarize the problem again, which angers the customer. How could the technician have better handled the situation to avoid such a confrontation?

- A. The technician should have asked the customer to slow down and allow for a response to a few of the matters brought up in discussion.
- B. The technician should have allowed the customer to finish completely, and then return to the customer's first point to build a structured discussion.
- C. The technician should have transferred the call to a supervisor, as the supervisor is better trained to handle such customers.
- D. The technician should have only asked closed-ended questions so the customer could not elaborate on the issues and the technician could troubleshoot the issue.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 95

When dealing with customers on the phone that are not very comfortable with technology, which of the following techniques would be MOST helpful to ensure that effective communication is taking place?

- A. Frequently paraphrase what the caller is saying.
- B. Repeat what is being said multiple times so that the customer can understand exactly what to do.
- C. Speak very slowly when replying to the customer.
- D. Tell the customer to send an email stating exactly what the problem is so that the communication between the two parties is clear.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 96

A technician is unable to find a solution for a customer's PC issue. Which of the following would be an appropriate step to take?

- A. Inform the customer that a solution is not available and a new system must be purchased.
- B. Escalate the call to a supervisor to register a complaint.
- C. Consult with co-workers for additional ideas.
- D. Refer the customer to the support section of the PC manufacturer's website.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 97

If a technician is getting frustrated during a support call, which of the following could the technician employ to

avoid irritating the customer?

- A. End the call quickly, even if a solution has not been found.
- B. Ask the caller to call back in a while.
- C. Put the caller on hold briefly and take a deep breath.
- D. Pass the caller to another support representative.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 98

A person calls in asking for the name of the vendor that the technician uses for the organization's firewall hardware. Which of the following is the BEST action for the technician to take?

- A. Immediately forward the call to the vendor.
- B. Give the information to the caller.
- C. Hang up on the caller immediately and report the call to upper management.
- D. Politely refuse to give the information and end the call.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

Exam D

QUESTION 99

A customer reports the optical drive is no longer responding. Which of the following questions should be asked FIRST?

- A. "Did you log in with an administrator account?"
- B. "Have you been to any inappropriate websites?"
- C. "What have you changed since the optical drive worked properly?"
- D. "What has changed since the optical drive worked properly?"

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 100

Which of the following is the MOST secure method to authenticate users?

- A. User ID, a strong password, and a fingerprint scanner
- B. User ID, a strong password, and a token based device
- C. User ID and two levels of strong password requirements
- D. User ID, a strong password, and a smart card

Correct Answer: A

Section: (none) Explanation

Explanation/Reference:

Exam B

QUESTION 1

A user states that they unplugged their mouse to clean the roller ball, but after plugging it back in the mouse no longer functions. Which of the following is the MOST likely cause of this issue?

- A. The mouse has a PS/2 connector which is not hot-swappable.
- B. The mouse roller ball is now too smooth to gain traction.
- C. The mouse was broken before the user unplugged to clean it.
- D. The mouse has a USB connector that is not getting enough power.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 2

When replacing a print head in an impact printer, special care MUST be given to adjustinG.

- A. the ribbon drive assembly
- B. the form thickness
- C. the platen gap
- D. the form length

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 3

A customer wants to use a Microsoft virtual solution on an existing high-end graphics workstation. Which of the following is required to accomplish this task?

- A. The motherboard must support PCI version 2.3 or above to use virtual technology.
- B. The motherboard BIOS must support virtual technology.
- C. The CPU L1 cache must have a minimum of 1 MB to support virtual technology.
- D. The chipset of the motherboard must have digitally signed drivers to work with virtual technology.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 4

Which of the following are components of an "active" CPU cooling solution?

- A. A heatsink and thermal compound.
- B. A heatsink, radiator, and thermal compound.
- C. A heatsink, attached fan, and thermal compound.

D. A heatsink, case fan, and thermal compound.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 5

A technician is asked to recommend hardware for a new computer for a graphic artist company that regularly uses 3-D animation software. Which of the following components should be chosen to BEST meet the customer's needs?

- A. Specialized video card
- B. Multi-core processor
- C. TV tuner/recorder
- D. Tape backup drive

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

Exam B

QUESTION 6

On a Windows XP machine, which of the following settings should be configured to allow dragging of files without holding the mouse button?

- A. ScrollLock
- B. StickyKeys
- C. MouseKeys
- D. ClickLock

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 7

A user states that they are trying to project their laptop to a screen for a presentation. They have plugged the projector cable into their laptop, and turned the projector on, but no signal is found. Which of the following should the technician perform FIRST?

- A. Ensure the projector is receiving power
- B. Verify the laptop is not running on battery
- C. Toggle the function key for displays
- D. Replace the projector cable with another

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 8

Which of the following is the MOST likely default configuration for a serial port?

- A. 8 Data bits, Odd Parity, 1 stop bit
- B. 8 Data bits, Even Parity, 2 stop bits
- C. 8 Data bits, No Parity, 1.5 Stop bits
- D. 8 Data bits, No Parity, 1 Stop bit

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following security threats are MOST likely prevented through user training?

- A. Network Intrusion
- B. Adware Popups
- C. Social Engineering
- D. Spam Messages

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Which of the following features are available in Windows 7 Professional beyond those available in Windows 7 Home Premium?

- A. HomeGroup
- B. Windows XP Mode
- C. Aero Desktop
- D. Internet Explorer 8

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 11

Which of the following are advantages of using Dynamic Host Configuration Protocol? (Select TWO).

- A. IP addresses can be managed from a central point
- B. Computers can automatically get new addressing when moved to a different network segment
- C. Media Access Control addresses can be changed automatically

- D. The network speed can automatically adjust based on the type of traffic being generated
- E. The HOSTS file on the computer can be validated for proper entries

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 12

Traffic coming across port 443 is for which of the following protocols?

- A. SFTP
- B. FTP
- C. HTTP
- D. HTTPS

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Which of the following are impact printers? (Select TWO).

- A. Line printer
- B. Dot matrix printer
- C. Thermal transfer printer
- D. Inkjet printer
- E. Xerographic printer

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 14

A user calls about a problem with receiving email. After troubleshooting the user's computer and finding nothing wrong, the technician contacts the email sender and finds out the user gave out their email address incorrectly. Which of the following is the BEST approach in explaining the issue to the user?

- A. "Sometimes computers are just strange, but it seems to be working now."
- B. "You gave them the wrong address and caused this problem."
- C. "The sender had the e-mail address wrong, but they have it correct now and the problem has been resolved."
- D. "The SMTP server was not getting a proper resolution of the recipient name field when it was parsing the header."

Correct Answer: C Section: (none)

Explanation

Explanation/Reference:

QUESTION 15

A technician would like to load an operating system CD on startup. Which of the following settings would a technician change in the BIOS?

- A. Enable TPM
- B. Enable BIOS password
- C. Disable TPM
- D. Boot sequence

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 16

Which of the following are supported bus widths for a PCIe bus slot? (Select TWO).

- A. 1x
- B. 3x
- C. 6x
- D. 16x
- E. 24x

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 17

Which of the following features make using WPA2 versus WEP a BETTER choice in a wireless environment?

- A. Ability to use multiple antennas to send and receive
- B. Ability to connect at a higher bandwidth
- C. Use of AES 256-bit encryption
- D. Lower traffic overhead makes transmissions faster

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 18

Which of the following BEST describes the function of hyperthreading support within a CPU?

- A. Allows the core to create a separate space to process threads
- B. Allows the processor to handle multiple threads per core
- C. Allows the core to shift to a higher clock speed based on thread count
- D. Allows the processor to reject certain threads to increase performance

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 19

Which of the following are PCIe slot types? (Select TWO).

- A. 2x
- B. 3x
- C. 4x
- D. 8x
- E. 16x

Correct Answer: CE Section: (none) Explanation

Explanation/Reference:

QUESTION 20

After creating backups of critical system and user data, which of the following is the BEST location to store the backups?

- A. In the supply closet so anyone can access them if needed
- B. Near the server for easy access to restore files
- C. Locked in a cabinet in the IT Manager's office
- D. At a secure off-site storage facility

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 21

Which of the following should a technician do FIRST in the BIOS to set up drive encryption?

- A. Enable eSATA support
- B. Run built-in diagnostics
- C. Enable TPM
- D. Enable virtualization support

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 22

During which of the following phases of the imaging process is the latent image exposed to toner?

- A. Charging
- B. Developing
- C. Exposing
- D. Transferring

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 23

An ISP has provided a DSL Internet connection with a static IP address. A technician is setting up a small office home office (SOHO) wireless router and needs to provide Internet access to five PCs on the network. Which of the following should be enabled?

- A. NAT
- B. WPS
- C. MAC filtering
- D. Port forwarding

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 24

Which of the following should be used to restrict access to a wireless network?

- A. Port forwarding
- B. Enable SSID broadcast
- C. Wireless encryption
- D. Enable DMZ

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 25

Which of the following devices would need to be configured to block specific ports and protocols from entering the network?

A. Bridge

- B. Firewall
- C. Port replicator
- D. Gateway

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 26

Which of the following displays uses gas as a method for projecting an image?

- A. CRT
- B. Plasma
- C. LED
- D. LCD

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 27

After a technician installs a video card, which of the following should the technician configure NEXT?

- A. Resolution
- B. Colors
- C. Dots per inch
- D. Refresh rate

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 28

Which of the following environmental factors are MOST important to monitor in order to protect computer equipment? (Select TWO).

- A. Temperature
- B. Intensity of lighting
- C. Barometric pressure
- D. Humidity level
- E. Elevation

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 29

A single office with five computers and a server is an example of which of the following?

- A. PAN
- B. WAN
- C. SAN
- D. LAN

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 30

Which of the following interfaces are used to simultaneously transfer video and audio at high rates?

- A. HDMI
- B. DVI-D
- C. S-Video
- D. DVI-I

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 31

A workstation would MOST likely be connected to an office network using which of the following cable types?

- A. eSATA
- B. Bluetooth
- C. SCSI
- D. Ethernet

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 32

Which of the following cables is normally associated with a DB-15 connector?

- A. STP
- B. VGA
- C. DVI
- D. RCA

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 33

Windows XP mode on a Windows 7 Professional machine fails to load. Which of the following is MOST likely the cause?

- A. The machine does not have enough processor cores to allow for this feature.
- B. Virtualization support is not enabled in the BIOS.
- C. A license of Windows XP must be purchased in order to use Windows XP Mode.
- D. The machine does not have enough RAM to allow for this feature.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 34

On a laptop, special operations like wireless card on/off, volume settings, and screen brightness can generally be controlled via which of the following physical means?

- A. Docking station toggle switches
- B. FN keys
- C. Remotes
- D. Up/down arrows

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 35

After setting up a new computer, a user states that the mouse and keyboard will not work. Which of the following is the MOST likely reason?

- A. The network cable is disconnected
- B. The PS/2 connectors are switched
- C. The USB connectors are switched
- D. The hard drive is unplugged

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 36

Which of the following processor socket types would support an AMD processor? (Select TWO).

- A. F
- B. LGA
- C. 940
- D. 775
- E. 1155

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 37

Which of the following would represent a power supply connector that supplies the main power to an ATX motherboard?

- A. 6-pin PCI connector
- B. 24-pin connector
- C. Molex connector
- D. SATA connector

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 38

Which of the following connector interfaces is MOST likely used to connect several peripheral devices such as printers, digital cameras, and scanners?

- A. Parallel
- B. USB
- C. Fibre
- D. SATA3

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 39

Which of the following is the appropriate interface to connect an optical mouse and keyboard to a computer?

- A. IEEE 1394
- B. USB
- C. Serial
- D. eSATA

Correct Answer: B
Section: (none)
Explanation

Explanation/Reference:

QUESTION 40

Which of the following laptop displays has a thinner design, consumes less power, and is not transparent?

- A. Plasma
- B. CCFL-backlit LCD
- C. OLED
- D. LED-backlit LCD

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 41

Which of the following transmits a digital signal?

- A. VGA
- B. XGA
- C. Component video
- D. DisplayPort

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 42

Which of the following laptop displays would provide physical flexibility and transparency?

- A. Standard LCD
- B. Plasma
- C. OLED
- D. LED-backlit LCD

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 43

Which of the following printers includes an imaging drum and fuser assembly?

- A. Laser
- B. Impact
- C. Inkjet
- D. Thermal

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 44

Which of the following parts of a laptop screen provides illumination for the LCD?

- A. Inverter
- B. Backlight
- C. Inverter connector cable
- D. Bezel

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 45

A user downloads a 4.1 GB ISO image from a website. Which of the following media types is required for the user to burn the image?

- A. CD+R
- B. BD-R
- C. DVD-ROM
- D. CD-ROM

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 46

Which of the following memory types is MOST commonly found in Pentium 4 class and newer desktop PCs?

- A. SIMM
- B. RAMBUS
- C. SODIMM
- D. DIMM

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 47

When designing a PC, which of the following components would help a large application load the FASTEST?

- A. Solid state drive
- B. 1 MB L2 cache memory
- C. High-end graphics card
- D. Dual core CPU

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 48

Which of the following would be the MINIMUM cable type that would allow a transmission speed of 1GB between two locations 250 meters (820 feet) apart?

- A. Multi-mode fiber
- B. CAT6
- C. CAT5e
- D. Single-mode fiber

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 49

When installing a new PCIe network card, when should manufacturer software and drivers be installed?

- A. Before inserting the PCIe network card in the case
- B. After inserting the new PCIe network card in the case
- C. They will be automatically loaded after installation
- D. Load them concurrently with the PCIe network card

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 50

Which of the following is a valid Class A TCP/IP address?

- A. 10.20.210.200
- B. 99.55.44.255
- C. 127.10.52.45

D. 172.24.168.20

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 51

Which of the following printing technologies uses piezoelectric pressure pads to produce small bubbles that are moved to the paper?

- A. Impact
- B. Thermal
- C. Laser
- D. Inkjet

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 52

Which of the following expansion cards is MOST likely to have a coaxial input?

- A. FireWire
- B. Video capture
- C. SATA
- D. TV tuner

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 53

Which of the following devices is MOST likely associated with MIDI?

- A. Synthesizer
- B. Modem
- C. Webcam
- D. Microphone

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 54

Which of the following configurations has the BEST performance capability?

- A. DDR without ECC
- B. DDR with ECC
- C. SDRAM without ECC
- D. SDRAM with ECC

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 55

Which of the following cable types is 68-pin?

- A. Floppy
- B. SCSI
- C. IEE1394
- D. IDE

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 56

Which of the following expansion cards can be installed into an AGP slot?

- A. Modem
- B. Network
- C. Video
- D. RAID

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 57

Which of the following voltages can be measured from a Molex connector on the power supply? (Select TWO).

- A. 1.5 volts
- B. 3 volts
- C. 5 volts
- D. 12 volts
- E. 115 volts

Correct Answer: CD Section: (none)

Explanation

Explanation/Reference:

QUESTION 58

Which of the following TCP/IP addresses is a Class C address?

- A. 10.0.0.1
- B. 12.78.1.1
- C. 172.16.1.1
- D. 192.168.1.1

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 59

Which of the following features on a wireless router maps the private IP address to a public IP address?

- A. SSID
- B. NAT
- C. MAC filtering
- D. DHCP

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 60

Which of the following offers the HIGHEST wireless security?

- A. WEP
- B. WPA2
- C. WPA
- D. HTTPS

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 61

Which of the following is used to deny or allow access to a wireless router network?

- A. SSID
- B. SNMP

- C. IMAP
- D. MAC filtering

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 62

Which of the following network media types uses laser light to carry the information?

- A. IEEE 1394
- B. STP
- C. RG-6
- D. Fiber

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 63

A home user working outside an office reports that their laptop is no longer connecting to the Internet. Which of the following would a technician recommend to check FIRST?

- A. Windows Firewall settings
- B. DHCP settings
- C. Disable HomeGroup
- D. Wireless on/off switch

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 64

Which of the following is BEST for providing network security?

- A. Firewall
- B. DMZ
- C. Switch
- D. IDS

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 65

A technician is not able to boot to Windows OS. A "Non-bootable device found" message appears on the screen when the computer restarts. Which of the following is the MOST possible cause of the error message?

- A. MBR is corrupt on the HDD.
- B. HDD is set to Cable Select.
- C. The operating system is corrupt.
- D. A bootable HDD is not recognized in the BIOS.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 66

A printer is not pulling paper out of the paper tray. Which of the following is the MOST possible cause of the problem?

- A. Pickup rollers
- B. Print head
- C. Drum
- D. Fuser

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 67

A technician has a PC that has no Internet connection. The IP address for the PC is 169.254.XXX.XXX. Which of the following should be checked FIRST?

- A. DHCP settings
- B. BIOS settings
- C. DNS settings
- D. Power settings

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 68

A laser printer prints pages with a gray background. Which of the following is the MOST possible cause of the problem?

- A. Transfer roller
- B. Paper type

- C. Print head
- D. Fuser

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 69

A technician installs a new sound card but no sound can be heard. Which of the following utilities can be used to see an error?

- A. MSCONFIG
- B. Device Manager
- C. DXDIAG
- D. REGEDIT

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 70

Which of the following is included in the typical laser printer maintenance kit? (Select TWO).

- A. Print head
- B. Toner
- C. Fuser
- D. Main drive assembly
- E. Pickup rollers

Correct Answer: CE Section: (none) Explanation

Explanation/Reference:

QUESTION 71

Which of the following connection types use a phone line as a carrier to provide access to the Internet? (Select TWO).

- A. Cellular
- B. Satellite
- C. ISDN
- D. WiMAX
- E. DSL

Correct Answer: CE Section: (none) Explanation

Explanation/Reference:

QUESTION 72

When upgrading BIOS firmware, which of the following limits are MOST commonly increased?

- A. CPU
- B. USB capacity
- C. Optical drive
- D. RAM

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 73

Which of the following is a multimedia device?

- A. Biometric device
- B. Mouse
- C. Camcorder
- D. Infrared scanner

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 74

Which of the following is the correct pin out for T568B?

- A. Orange/white, orange, green/white, blue, blue/white, green, brown/white, brown
- B. Blue, blue/white, orange/white, orange, brown/white, brown, green/white, green
- C. Green/white, green, orange/white, blue, blue/white, orange, brown/white, brown
- D. Orange/white, orange, brown/white, brown, green/white, green, blue, blue/white

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 75

Which of the following 802.11 standards can operate at both 2.4 GHz and 5.0 GHz?

- A. A
- B. B
- C. G

D. N

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 76

Which of the following connector types uses a single RCA style connector?

- A. DVI
- B. VGA
- C. RGB
- D. Composite video

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 77

Which of the following devices would allow a technician to utilize a single mouse, keyboard, and display to control numerous desktop PCs?

- A. Port replicator
- B. Docking station
- C. USB hub
- D. KVM switch

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 78

A service technician suspects the fuser assembly needs to be replaced. Which of the following is MOST likely the type of printer being repaired?

- A. Inkjet
- B. Laser
- C. Impact
- D. Thermal

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 79

Which of the following RAID levels requires ONLY two drives and provides mirroring?

- A. RAID 0
- B. RAID 1
- C. RAID 5
- D. RAID 10

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 80

A frustrated and angry customer calls in with a system that does not work. Which of the following is the FIRST course of action for a technician to take?

- A. Transfer the customer to another technician, who can allocate more time to the issue.
- B. Maintain a positive attitude and offer them the cheapest solution possible to satisfy them.
- C. Listen to what the customer has to say and calmly recommend the best course of action.
- D. Use technical language to demonstrate knowledge and expertise to the customer.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 81

Proper lifting technique for heavy items is:

- A. to use gloves to pick up the item.
- B. to squat and lift from the legs.
- C. to have two people bend down and pick the item up.
- D. to bend down and lift the item up.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 82

A technician needs to replace a computer's hard drive. Which of the following should the technician do FIRST?

- A. Remove network connections
- B. Remove the RAM
- C. Self ground on the computer case
- D. Disconnect power to PC

Correct Answer: D

Section:	(none)
Explanat	ion

Explanation/Reference:

QUESTION 83

When a grounding strap is not available, a technician can ground by touching the computer's:

- A. power supply.
- B. CPU fan.
- C. memory chips.
- D. motherboard.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 84

Which of the following features would hide internal IP addresses from the Internet?

- A. Network Address Translation
- B. Port forwarding
- C. Quality of Service
- D. SSID broadcast

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 85

A technician needs to configure a computer with an external storage drive. Which of the following interfaces would provide the FASTEST throughput?

- A. USB 2.0
- B. eSATA
- C. CAT5
- D. FireWire

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 86

A bank wants to maximize the security of employee computer data displayed on their screen. Which of the following would BEST accomplish these goals?

- A. Keyboard filters
- B. Privacy filters
- C. Screensavers
- D. Secure display drivers

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 87

Which of the following laptop displays would provide the BEST viewing angle?

- A. IPS LCD
- B. TFT LCD
- C. DLP
- D. Plasma

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 88

Two new PCs will have a DVD-RW drive for support use. The PCs will be used for Point of Sales transactions and everything will be password protected or disabled. Which of the following is the BEST way to disable the DVD-RW drives?

- A. The Registry
- B. Device Manager
- C. Disk Management
- D. The BIOS

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 89

A customer has a QUESTION about the repairs needed for their desktop computer. While asking their QUESTION to a technician, the technician receives a personal phone call on their cell phone. Which of the following should the technician do NEXT?

- A. Ask the customer to wait and answer the phone call.
- B. Talk on the phone while listening to the customer.
- C. Hand the phone to a coworker to answer the call.
- D. Silence the phone and then listen to the customer.

Correct Answer: D

Section: (none) Explanation

Explanation/Reference:

QUESTION 90

A technician has just finished installing a new NIC into a customer's desktop. Which of the following should the technician do NEXT?

- A. Perform a full system backup.
- B. Follow up with the customer, verifying satisfaction.
- C. Ask their manager to contact the customer.
- D. Perform a complimentary virus scan.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 91

A technician replaces a computer's NIC with a wireless card. The user wants to save the NIC. Which of the following should the technician use to preserve the NIC?

- A. ESD mat
- B. ESD wrist strap
- C. Sealable plastic bag
- D. Anti-static bag

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 92

Which of the following protocols would be used in order to log into a router to configure a VLAN?

- A. RDP
- B. SMTP
- C. TELNET
- D. FTP

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 93

A user has a new network printer they want setup in their home. The user wants all their PCs as well as any guests with laptops to be able to print to it. Which of the following connection methods would be the MOST

effective for meeting these requirements? (Select TWO).

- A. 802.11g
- B. USB
- C. Ethernet
- D. Bluetooth
- E. Serial

Correct Answer: AC Section: (none) Explanation

Explanation/Reference:

QUESTION 94

Which of the following laptop components will MOST likely need replacing within the first three years of use?

- A. Battery
- B. Processor
- C. Memory
- D. Backlight

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 95

A user states that their laser printer prints black and white streaks about half an inch wide down the left side of every page. Which of the following components MOST likely needs replacing?

- A. Toner
- B. Transfer roller
- C. Fuser
- D. Pickup assembly

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 96

When connecting a PC to a television in order to stream a movie, which of the following connector types would only need one cable?

- A. DVI-D
- B. IEEE 1394b
- C. HDMI
- D. USB 3.0

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

Exam C

QUESTION 97

A technician is servicing the Human Resource director's computer which contains payroll software and salary information. Which of the following should the technician do to ensure confidentiality of the payroll information?

- A. Backup the confidential data to the technician's USB drive to ensure nothing is accidently deleted.
- B. Uninstall the payroll software to ensure confidentiality.
- C. Have the director remove sensitive data before the computer will be repaired.
- D. Perform needed repairs while avoiding sensitive data.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 98

After installing a new optical drive into a workstation, which of the following will ask for an acknowledgement?

- A. IRQ Manager
- B. BIOS
- C. Device Manager
- D. Hardware Compatibility List

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 99

A user's laptop does not produce sound even though the volume settings are at maximum in the operating system. Which of the following would MOST likely resolve this issue?

- A. A new sound card
- B. A new speaker
- C. A BIOS update
- D. A hardware volume control

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 100

When a user's computer is first turned on, they see a lock symbol and a blinking cursor. Which of the following

was configured in the BIOS to show this?

- A. Intrusion detection
- B. Power on password
- C. Drive encryption
- D. BIOS password

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

Exam C

QUESTION 1

A technician arrives in Germany and discovers that when their PC is plugged into the outlet, no power is received. Which of the following actions should the technician take to get the PC to operate?

- A. Change the BIOS settings to the local time
- B. Adjust the voltage selector switch
- C. Attach a 220 volt power strip from the current region to the PC
- D. Attach a 120 volt battery backup power supply to the PC

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following BIOS level settings allow an administrator to view warnings on possible hardware level changes?

- A. Drive lock
- B. Intrusion detection
- C. BIOS password
- D. Trusted platform module

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 3

A user can no longer launch their word processing program. The program worked fine yesterday. Which of the following options could BEST be used to fix the word processing program?

- A. Safe Mode
- B. Automated System Recovery
- C. Last Known Good Configuration
- D. System Restore

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 4

A technician installs a new video card in a desktop with onboard video. The technician boots the unit but sees no display. The monitor power light is on and the OS seems to be loading. Which of the following is the MOST likely cause?

A. The display is defective.

- B. The video card needs to be flashed.
- C. The internal adapter has not been disabled.
- D. The new video card is defective.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Which of the following adapter cards allows I/O devices to be connected and transmits data using a POTS line?

- A. PCI tuner card
- B. PCI modem
- C. PCI SCSI
- D. PCI Ethernet

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 6

The contrast ratio for an LCD monitor is BEST defined as the ratio between:

- A. display resolution and brightness.
- B. power consumption and output intensity.
- C. power savings of a comparable CRT monitor and the LCD.
- D. the darkest and lightest displayed output.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Which of the following technologies is the MOST secure form of wireless encryption?

- A. SSL
- B. WPA
- C. WEP
- D. TLS

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 8

Which of the following WLAN protocols is in the 5GHz band with a MAXIMUM data rate of 54Mbps?

- A. 802.11a
- B. 802.11b
- C. 802.11g
- D. 802.11n

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following malicious software types will create multiple pop-ups on a computer?

- A. Adware
- B. Grayware
- C. Worms
- D. Spyware

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 10

The technician is repairing a PC which appears to have a failing RAM module. After replacing the module, the extra memory still is not registering. Which of the following is MOST likely the issue?

- A. Jumper settings are incorrect
- B. The RAM module is defective
- C. The memory slot is defective
- D. CMOS needs to be flashed

Correct Answer: C Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/

Which of the following processing types allows two instructions to be received and processed nanoseconds apart?

- A. Quad core
- B. Triple core
- C. Dual core
- D. Hyper-threading

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 12

Which of the following operating system types will allow a user to utilize 16GB of RAM if installed on a PC workstation?

- A. 8-bit
- B. 16-bit
- C. 32-bit
- D. 64-bit

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Which of the following expansion devices would allow a user to utilize multiple hardware profiles to control an external display and power option?

- A. PCI Express card
- B. KVM
- C. PCMCIA card
- D. Docking station

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 14

Which of the following devices is used to move frames between a source and destination based on a MAC address?

- A. Repeater
- B. Hub
- C. Router
- D. Switch

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 15

A technician just installed an antivirus suite on a workstation. It is kept up-to-date and has recently scanned the system. A day later the user reports slower response times than usual. Which of the following is the user MOST likely experiencing?

- A. Advertisements
- B. Resource consumption
- C. A trojan infection
- D. Unremoved viruses

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 16

Which of the following protocols encrypt communication? (Select TWO).

- A. HTTPS
- B. TELNET
- C. SMTP
- D. DNS
- E. SSH

Correct Answer: AE Section: (none) Explanation

Explanation/Reference:

QUESTION 17

A user wants to install a new game and needs to make sure the proper version of DirectX is installed. Which of the following is the BEST way to check for the DirectX version?

- A. REGEDIT
- B. services.msc
- C. Dxdiag
- D. msconfig

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 18

Which of the following methods can be used to apply a file system to a hard drive partition? (Select TWO).

- A. Device Manager MMC
- B. Format Command
- C. Disk Management MMC
- D. Windows Explorer Menus
- E. FDISK Command

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 19

A user is having problems printing. The technician believes the printer may be out of ink. Which of the following troubleshooting steps should be performed NEXT?

- A. Establish a plan of action to resolve the problem
- B. Implement the solution
- C. Test the theory to determine cause
- D. Verify full system functionality

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 20

A Windows XP Professional PC needs to be checked for compatibility before being upgraded to Windows Vista Business. Which of the following would be the BEST action to take before the upgrade?

- A. Run the Windows Vista Upgrade Advisor on the target PC.
- B. Check the README file on the Vista installation DVD for system requirements.
- C. Check the manufacturer's support pages for system requirements.
- D. Run the Windows AlK on the Vista installation DVD.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 21

Which of the following is the NEXT step in the troubleshooting theory after identifying the problem?

- A. Establish a theory of probable cause
- B. Test the theory
- C. Implement preventative measures

D. Establish a plan of action

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 22

Which of the following media types is considered a solid state?

- A. Thumb drive
- B. DVD drive
- C. Blu-Ray drive
- D. IDE FDD

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 23

A technician replaces a user's 15 inch LCD with a 20 inch LCD. Later, the user informs the technician that icons are very large and the text on the monitor is fuzzy and distorted. Which of the following is MOST likely the cause?

- A. The contrast setting needs to be raised from the default.
- B. The monitor firmware was not updated.
- C. The new monitor has a different native resolution.
- D. The monitor needs to be degaussed to clarify the picture.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 24

On which of the following transmission media types can LC connectors be found?

- A. UTP
- B. STP
- C. Coaxial
- D. Fiber

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 25

Which of the following BEST describes a hub?

- A. Determines the best route to transmit data
- B. Inspects traffic and accepts or declines transmission
- C. Broadcasts data to specific network devices
- D. Broadcasts data to all network devices

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 26

Which of the following is the MOST common secure web server port?

- A. 22
- B. 80
- C. 110
- D. 443

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 27

Which of the following protocols would BEST grant the user secure access to a remote location?

- A. VPN
- B. FTP
- C. POP3
- D. DNS

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 28

Which of the following network connections would use a standard POTS line to both send and receive Internet packets? (Select TWO).

- A. Dial-up
- B. DSL
- C. Satellite
- D. OC3
- E. T1

Correct Answer: AB Section: (none) Explanation

Explanation/Reference:

QUESTION 29

A user has purchased a laptop that has no means to charge the battery. Which of the following would the user MOST likely purchase?

- A. USB cable
- B. AC adapter
- C. PCMCIA card
- D. Replacement battery

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 30

A technician dropped a screw in the case of a desktop computer. Which of the following tools should be used to retrieve the screws?

- A. Computer vacuum
- B. Plastic tweezers
- C. Canned air
- D. Screwdriver with magnetized tip

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 31

Which of the following is needed to boot into the Recovery Console in Windows XP?

- A. Emergency Restore Disk
- B. System Restore point
- C. Original Installation CD
- D. Automated System Recovery

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 32

Which of the following tools is an advanced option of the Windows XP backup tool?

- A. Emergency Repair Disk
- B. Recovery Console
- C. Disk Probe
- D. Automated System Recovery

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 33

Which of the following command prompt utilities displays the current version of Windows XP and any Service Packs that are installed?

- A. CHECKVER.EXE
- B. VERSION.EXE
- C. SIGVERIF.EXE
- D. WINVER.EXE

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 34

Which of the following wireless security techniques is the MOST secure?

- A. Enable Wired Equivalent Privacy
- B. Disable SSID broadcast
- C. Enable Wi-Fi Protected Access
- D. Enable MAC filtering

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 35

Which of the following would be the BEST resolution setting for an application that requires a minimum resolution of 1024 x 768?

- A. SVGA
- B. PAL
- C. VGA
- D. XGA

Correct Answer: D Section: (none)

Explanation

Explanation/Reference:

QUESTION 36

Which of the following will help dissipate heat through the heat sink when upgrading a CPU?

- A. Case fan
- B. Thermal compound
- C. Motherboard riser
- D. Power supply

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 37

A client states they are receiving poor signal strength on their wireless Internet connection. Which of the following is MOST likely causing the interference? (Select TWO).

- A. Cordless phones
- B. Drywall
- C. Access points
- D. Microwaves
- E. Fluorescents lights

Correct Answer: AD Section: (none) Explanation

Explanation/Reference:

QUESTION 38

A user reports that their UPS is making a loud beeping sound. Which of the following would cause this problem?

- A. The UPS is overcharged.
- B. Incorrect wattage on the power supply.
- C. The UPS battery is not charged.
- D. The UPS is in power management mode.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 39

A technician just finished installing a new printer on an end user's computer. Which of the following will enable the technician to see the test page option for the printer?

- A. Right-click on the printer and select Properties
- B. Double click on the printer icon
- C. Right-click on the printer and select Set as Default
- D. Right-click on the printer and select Open

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 40

An end user reports that their computer is making noise constantly. The technician notes that the hard drive activity light is on frequently. The technician finds plenty of free space on the drive. Which of the following BEST explains why the drive light is continuously active?

- A. The system has a fragmented hard drive.
- B. The drive interface needs to be changed.
- C. The user has too many documents on the hard drive.
- D. The system page file has an issue.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 41

A customer states their computer was fine until yesterday when they heard a pop noise and the computer stopped working. Which of the following components should the technician test FIRST?

- A. Main system board
- B. Processor
- C. Hard disk drive
- D. Power supply

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 42

A customer's computer crashes consistently when a specific application is launched. The technician has looked at the computer and confirmed the cause of the crash. Which of the following is the NEXT troubleshooting step the technician should take?

- A. Verify full system functionality.
- B. Document the findings, actions, and outcomes.
- C. Establish a plan of action to resolve the problem.
- D. QUESTION the user and identify changes the user has made to the system.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 43

Hyperthreading technology:

- A. only works on computer systems with multiple core CPUs.
- B. enables a processor to work with two independent computer instructions at once.
- C. enables two independent processors to work on the same task, simultaneously.
- D. allows a computer program to work on multiple tasks simultaneously.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 44

Which of the following services processes print requests and sends them to the printer?

- A. Printer Driver
- B. Print Spooler
- C. Printer Service
- D. Print Properties

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 45

Which of the following ports is BEST to use when adding a network printer in Windows XP?

- A. USB
- B. COM5
- C. LPT1
- D. TCP/IP

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 46

Which of the following is an advantage that a USB mouse has over a PS/2 mouse?

- A. A USB mouse uses less power
- B. A USB mouse is more portable
- C. A USB mouse is hot swappable
- D. A USB mouse is more secure

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 47

The user turns on the computer and hears a popping sound and detects a burning smell. The system will not power on. Which of the following is the MOST likely problem?

- A. Power supply has blown.
- B. CPU fan is faulty.
- C. Motherboard has overheated and shutdown.
- D. UPS has been tripped.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 48

After plugging in and installing drivers for a wireless bar code reader, which of the following is the LAST step needed to configure the device?

- A. Install an inventory tracking application.
- B. Scan the bar code on the reader's cradle.
- C. Enable the device in Device Manager.
- D. Remove any temporary device drivers.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 49

Which of the following broadband types can provide the MOST available bandwidth?

- A. DSL
- B. Fiber
- C. Satellite
- D. Cable

Correct Answer: B Section: (none) Explanation

QUESTION 50

A user received an email from their bank asking them to login and verify their personal information. The user complies and fills in the requested information. Days later the user notices their checking account is empty. This is a result of which of the following?

- A. Spam
- B. Phishing
- C. Adware
- D. A Trojan

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 51

Which of the following devices would MOST likely require a serial adapter to be installed on a modern PC?

- A. External modem
- B. TV tuner
- C. Mouse
- D. Keyboard

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 52

Which of the following can be hot-swappable?

- A. Hard drive
- B. Tape drive
- C. Floppy drive
- D. DVD-RW

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 53

Which of the following technologies has the HIGHEST potential throughput?

A. DSL

- B. Fiber
- C. Satellite
- D. Cable

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 54

Which of the following utilities would a technician use to determine network utilization?

- A. Start Menu
- B. My Network Places
- C. Administrative Tools
- D. Task Manager

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 55

Which type of connector is required for a coaxial network cable?

- A. RJ-11
- B. Token ring
- C. BNC
- D. RJ-45

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 56

Which of the following memory modules uses a 240-pin connector?

- A. DDR
- B. SIMM
- C. DDR2
- D. RAMBUS

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 57

Which of the following are potential sources of EMI? (Select TWO).

- A. Strong magnets
- B. Toaster ovens
- C. Cordless phones
- D. Flat panel TVs
- E. AC power runs

Correct Answer: AE Section: (none) Explanation

Explanation/Reference:

QUESTION 58

While accessing the Internet in an external environment (i.e. while traveling), a Windows 7 firewall should be set to which of the following?

- A. Block incoming and outgoing connections
- B. Turned off or disabled
- C. Block outgoing connections
- D. Block incoming connections

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 59

Which of the following drive connections uses a ribbon cable with a 40-pin connector? (Select TWO).

- A. SATA
- B. IDE
- C. PATA
- D. FDD
- E. SCSI

Correct Answer: BC Section: (none) Explanation

Explanation/Reference:

QUESTION 60

Which of the following is a characteristic of a serial I/O port?

- A. RJ-11 connector
- B. DB-15 connector
- C. DB-9 connector

D. RJ-45 connector **Correct Answer:** C Section: (none) **Explanation Explanation/Reference: QUESTION 61** Which of the following is the default HTTPS port? A. 25 B. 80 C. 110 D. 443 Correct Answer: D Section: (none) **Explanation Explanation/Reference: QUESTION 62** Which of the following types of software protection will help mitigate any threats coming from worms or Trojans? A. Spam blocker B. Anti-Virus C. Anti Spyware D. Anti adware Correct Answer: B Section: (none) **Explanation Explanation/Reference: QUESTION 63** An optical disc with a 4.7GB MAXIMUM storage capacity is likely which of the following technologies? A. DVD-RW B. CD-RW C. BD-ROM D. BD-RW **Correct Answer:** A Section: (none) **Explanation**

QUESTION 64

Explanation/Reference:

From which of the following locations can a technician map a drive?

- A. System Properties
- B. Help and Support Center
- C. Add Hardware Wizard
- D. My Computer

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 65

Which of the following characteristics must be matched depending on the specifications of the power grid for the country a PSU will be utilized in?

- A. Wattage
- B. Amperage
- C. Resistance
- D. Voltage

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 66

Modern desktop computer systems require the following to properly dissipate heat (Select TWO):

- A. Temperature Control Panel
- B. Thermal Compound
- C. Liquid Cooling Systems
- D. Processor Heat Sink
- E. Case Fan

Correct Answer: BD Section: (none) Explanation

Explanation/Reference:

QUESTION 67

A memory type typically used in high end workstations and not generally found in consumer grade PCs is:

- A. DDR3.
- B. ECC.
- C. PC2-6400.
- D. DDR2-667.

Correct Answer: B

Section: (none) Explanation

Explanation/Reference:

QUESTION 68

A user reports that their hard drive has failed and needs to be replaced. Which of the following should the technician do FIRST?

- A. Run the hard disk manufacturer's diagnostic program
- B. Re-image the drive
- C. Replace the hard drive and load Windows
- D. Ask the user diagnostic questions

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 69

A manufacturer has instructed a technician to update the software that resides on the flash ROM chip of an integral system add-in component. Which of the following types of software needs to be updated?

- A. System BIOS
- B. Firmware
- C. OS Patch
- D. Driver

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 70

Which of the following steps would be performed FIRST to install a fresh copy of Windows 7 Professional on a new hard drive?

- A. Format the partition
- B. Load any RAID or SATA drivers needed
- C. Partition the drive
- D. Configure Windows settings

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 71

Which of the following occurs during POST?

- A. OS loads
- B. Safe Mode starts
- C. RAM check
- D. MBR check

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 72

Which of the following Internet technologies has the slowest potential upload speed due to inherent latency issues?

- A. 3G
- B. 4G
- C. Satellite
- D. Fiber

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 73

Which of the following is the correct connector for an internal floppy drive?

- A. 50-pin SCSI
- B. 40-pin ribbon
- C. 34-pin ribbon
- D. 4-pin SATA

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 74

A company printer is used to print payroll checks on paper forms with carbon backing. Which of the following is the BEST type of printer for this scenario?

- A. Laser
- B. Impact
- C. Inkjet
- D. Thermal

Correct Answer: B Section: (none)

Explanation

Explanation/Reference:

QUESTION 75

A technician has had several support requests for one PC. The technician has reseated the PCI cards and replaced the hard drive in the PC located in a school cafeteria kitchen. PCs located in the business office or the classrooms have not had this issue. Which of the following is MOST likely causing this PC's issue?

- A. Faulty RAM
- B. 240 volt Kitchen outlets
- C. Power Brownouts
- D. Excessive Heat

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 76

Which of the following ports is the default for HTTP?

- A. 21
- B. 25
- C. 80
- D. 110

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 77

Which of the following printers requires a specialized paper in order to operate?

- A. Thermal
- B. Laser
- C. Inkjet
- D. Impact

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 78

A user reports that they walked away from their laptop for 30 minutes and when they came back the screen was very dim. The user tried moving the mouse and increasing the brightness setting, but neither worked. Which of the following should the technician do FIRST?

- A. Plug in an external monitor to test the video card.
- B. Run a check disk scan to verify there is no corruption.
- C. Check if the laptop is now on battery power.
- D. Have the LCD screen replaced with a known good screen.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 79

A user reports that their touchpad no longer works on their laptop. Which of the following is the FIRST troubleshooting step?

- A. Plug in USB keyboard
- B. Check for a disable switch
- C. Contact the laptop manufacturer
- D. Plug in a USB mouse

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 80

Users in an office routinely work with large graphics files. Which of the following preventive maintenance tools can assist in maintaining system performance?

- A. FPROT
- B. DEFRAG
- C. CHKDSK
- D. SFC

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 81

A user discovers that color laser prints are printing slightly off-color. Which of the following should help restore the appropriate colors?

- A. Use different paper
- B. Replace the fuser
- C. Replace the duplexer
- D. Calibrate the printer

Correct Answer: D

Section:	(none)
Explanati	ion

QUESTION 82

Which of the following devices on a home network should be placed in a DMZ?

- A. Backup server
- B. Gaming server
- C. Smartphone
- D. Wireless printer

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 83

A Windows 7 user has documents spread throughout multiple hard drives and wishes to organize and search them in one panel. Which of the following features should they be shown?

- A. Windows Explorer
- B. My documents
- C. Windows Desktop Search 4.0
- D. Libraries

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 84

ECC memory is primarily used in which of the following computers?

- A. Tablet
- B. Desktop
- C. Server
- D. Laptop

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 85

Which of the following connectors is commonly used on a shielded twisted pair cable?

A. BNC

- B. RJ-45
- C. F
- D. HDMI

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 86

A technician has installed a new driver on a computer. Upon rebooting the computer, a stop error occurs before the technician can log back in. Which of the following would be the BEST option for the technician to do NEXT?

- A. Boot the computer to the Recovery Console.
- B. Boot the computer with a Windows Installation CD.
- C. Boot the computer using Last Known Good Configuration.
- D. Boot the computer using Safe Mode with Networking.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 87

Which of the following is the MAXIMUM cable length for 802.3 Ethernet?

- A. 33 Feet (10 meters)
- B. 100 Feet (30 meters)
- C. 328 Feet (100 meters)
- D. 1200 Feet (366 meters)

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 88

Which of the following commands can be used to verify the gateway IP address on a local computer?

- A. net use
- B. telnet
- C. ping
- D. ipconfig

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 89

Which of the following uses pair authentication to provide a wireless connection between two devices?

- A. 802.11n
- B. Bluetooth
- C. Infrared
- D. Cellular

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 90

Which of the following wireless standards provides the FASTEST speed?

- A. 802.11a
- B. 802.11b
- C. 802.11g
- D. 802.11n

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 91

A PC technician must upgrade memory from 2 GB to 4 GB in twenty Windows 7 notebook computers. Some of the laptops have DDR2 memory, and some have DDR3. The memory purchased for the upgrade is DDR3. Which of the following is the MOST likely outcome of this upgrade?

- A. The DDR2 notebooks will work with DDR3 provided the DDR2 is installed in the first DIMM positions.
- B. The DDR3 notebooks are the only ones that will accept the new memory.
- C. The DDR2 memory will fit into the DIMM positions and work.
- D. The DDR3 memory will not work correctly unless the CAS (CL) values are the same.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 92

Which of the following devices converts digital signals to analog ones?

- A. Modem
- B. Switch
- C. Hub

D. Router
Correct Answer: A Section: (none) Explanation
Explanation/Reference:
QUESTION 93 Which of the following encryption types would be the MOST secure?
A. WPA2 TKIP B. WEP C. WPA2 AES D. WPA
Correct Answer: C Section: (none) Explanation
Explanation/Reference:
QUESTION 94 Which of the following utilities would be used to configure energy saving measures when a laptop switches to battery power?
A. MSTSC B. ACPI C. GDI D. MSCONFIG
Correct Answer: B Section: (none) Explanation
Explanation/Reference:
QUESTION 95 Which of the following protocols is used to assign an IP address to a host?
A. FTP B. ATAPI C. DNS D. DHCP
Correct Answer: D Section: (none) Explanation

QUESTION 96

Explanation/Reference:

Which of the following protocols would be used to upload files to a web server?

- A. IMAP
- B. FTP
- C. SMTP
- D. ICMP

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 97

A DSL modem uses which of the following media?

- A. Cable TV coax
- B. Fiber optic cable
- C. Wireless adapter
- D. Household telephone lines

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 98

A technician installs an additional hard drive controller. Which of the following processes will MOST likely prevent errors?

- A. 1) Apply System Updates
 - 2) Update the BIOS
 - 3) Install the card
 - 4) Install the driver
 - 5) Upgrade the Card Firmware
- B. 1) Install the card
 - 2) Update the BIOS
 - 3) Upgrade the Card Firmware
 - 4) Install the driver
 - 5) Apply System Updates
- C. 1) Apply System Updates
 - 2) Install the driver
 - 3) Install the card
 - 4) Upgrade the Card Firmware
 - 5) Update the BIOS
- D. 1) Update the BIOS
 - 2) Install the driver
 - 3) Install the card
 - 4) Upgrade the Card Firmware
 - 5) Apply System Updates

Correct Answer: A Section: (none)

Explanation

Explanation/Reference:

QUESTION 99

A user states that whenever they try to launch a certain installed application, they hear unusual whirring/ clicking sounds from their machine and the application never loads. Which of the following components would a technician MOST likely need to replace?

- A. Hard Disk Drive
- B. Optical Drive
- C. Power Supply Unit
- D. Case Fan

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 100

What is the MINIMUM Windows Experience Index recommended for using Aero enhancements in Windows 7?

- A. 2.0
- B. 3.0
- C. 4.0
- D. 5.0

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

Exam D

QUESTION 1

Which of the following cables can be used to directly connect a laptop to a PC for ICS?

- A. IEEE 1394 cable
- B. CAT5 crossover cable
- C. CAT5e patch cable
- D. Parallel cable

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following would be used to monitor unauthorized access to data files?

- A. Performance Log and Alerts
- B. Event Viewer
- C. Security Configuration and Analysis
- D. IP Security Monitor

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 3

Which of the following connectors uses the main board ATX connector type?

- A. Centronix
- B. 20/24 pin
- C. BNC
- D. Molex

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 4

A frustrated customer has called about their computer that is not functioning correctly. Which of the following is the BEST QUESTION to ask the user?

- A. "Can you avoid using the PC that crashed?"
- B. "What was the last thing that occurred before the PC had problems?"
- C. "What were you doing before the PC went down?"
- D. "What was the last thing you did before the PC crashed?"

Correct Answer: B
Section: (none)
Explanation

QUESTION 5

When setting up a new small office home office (SOHO) wireless network, which of the following is MOST likely to be the default wireless channel?

- A. 2
- B. 5
- C. 6
- D. 9

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Which of the following passive cooling methods BEST dissipates a component's heat?

- A. Heatsink
- B. Fan
- C. Liquid cooling
- D. Compressed air

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 7

Which of the following has the speed of PC133?

- A. SDRAM
- B. RAMBUS
- C. DDR2
- D. DDR

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 8

Which of the following characteristics is true of a PCIe x8 card?

- A. It can use only IRQ8.
- B. It uses eight memory addresses for storage of data.
- C. It has eight lanes by which data is transmitted.
- D. It has eight times the bandwidth of a standard PCI card.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following attributes is set when a file is ready to be backed up?

- A. a
- B. h
- C. r
- D. s

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 10

Which of the following is an example of a hot swappable component on a laptop?

- A. Internal wireless adapter
- B. CPU
- C. PCMCIA card
- D. RAM

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 11

A user wants to install an external hard drive using the fastest connection available. Which of the following should the technician recommend?

- A. USB 1.1
- B. eSATA
- C. USB 2.0
- D. IEEE 1394

Correct Answer: B Section: (none) Explanation

QUESTION 12

Which of the following describes the random access memory limitations with Vista 64-bit operating system?

- A. 2GB
- B. 4GB
- C. 8GB
- D. 128GB

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 13

A user's OS has become corrupt, and the user would like to restore the PC back to when they first bought the machine. Which of the following would be the BEST choice?

- A. Factory Recovery Partition
- B. Use Safe Mode
- C. Last Known Good Configuration
- D. Purchase a copy of the original OS

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 14

A laser printer has an error `tray two paper jam' but tray two does not have any paper in it. Which of the following should the technician do FIRST?

- A. Replace the tray two paper sensor and run the printer self test.
- B. Remove the tray two paper sensor and clean the printhead.
- C. Check the tray two paper sensors for blockage and run the printer self test.
- D. Check the tray two paper rollers for blockage, clean the printhead, and run the printer self test.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 15

A user explains that after the office was vacuumed the previous night their sound is not working and they cannot get onto the network. The user has verified that all of the PC's cables are plugged into their respective ports. Which of the following is the MOST likely cause?

- A. Frayed or broken cables
- B. UPS is unplugged
- C. NIC and sound card are disabled in Device Manager
- D. Speakers are muted

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 16

An end user reports that their computer is not performing as fast as it used to and it shuts down unexpectedly. Which of the following is the MOST likely cause?

- A. Network data cables are damaged.
- B. Memory has become unseated.
- C. The user has defragmented the hard drive.
- D. Processor cooling fan is not functioning.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 17

A technician needs to upgrade the memory in a laptop. Which of the following memory types would be the correct type?

- A. RIMM
- B. DDR RAM
- C. SDRAM
- D. SODIMM

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 18

After hardware upgrades have been installed, the technician boots the computer system. No display output is observed but a beeping is heard from the computer. Which of the following is the MOST likely issue?

- A. Hard drive cables are not connected.
- B. BIOS chips are not seated properly.
- C. The power supply is not functioning.
- D. Video card is not seated properly.

Correct Answer: D Section: (none)

Explanation

Explanation/Reference:

QUESTION 19

Which of the following safety procedures is the BEST when lifting heavy equipment onto a repair bench?

- A. The technician should always bend at the waist and lift with their arms.
- B. The technician should seek assistance from an available customer.
- C. The technician should always bend at the waist and lift with their back.
- D. The technician should get assistance from another technician.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 20

Which of the following connectors is MOST commonly used for UTP cable?

- A. RJ-45
- B. RJ-11
- C. LC
- D. SC

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 21

A dry cleaner is having issues with their computer overheating. Which of the following preventive maintenance techniques would be the BEST short-term resolution to the problem?

- A. Update the firmware on the machine to accommodate for higher temperatures.
- B. Use Disk Cleanup and Defrag to keep the machine from working as hard.
- C. Use a can of compressed air to clean out blocked ventilation.
- D. Relocate the machine to a cooler part of the building.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 22

A Denial of Service (DoS) attack is:

A. an attempt to bring down a website or other online service.

- B. a prank where someone sends an unauthorized e-mail attempting to close a user's e-mail account.
- C. stealing a user's identity and making changes to their accounts.
- D. an attempt to change a user's password to prevent access to a service by repeatedly guessing the user's information.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 23

Which of the following BEST describes the purpose of user account control (UAC) in Windows Vista?

- A. UAC ensures that standard users cannot access the files and folders of administrative users.
- B. UAC allows a computer administrator to add new user accounts to the system, configure passwords and settings for existing users, or remove existing user accounts.
- C. UAC ensures that viruses and other malware cannot infect the computer, eliminating the need for third-party antivirus solutions.
- D. UAC ensures that important changes cannot be made to Windows Vista without the permission of a computer administrator.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 24

A technician is trying to install a previous-generation expansion card into their new laptop. However, the card refuses to fit into the expansion slot. Which of the following is MOST likely the reason?

- A. The card needs to have the compatibility jumpers set before it can be installed into the system.
- B. The card is a PCI Express card and the laptop supports PCMCIA.
- C. The expansion slot needs to be enabled in the BIOS first.
- D. The card is a PCMCIA card and the laptop supports PCI Express cards.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 25

Which of the following would BEST optimize a computer that is heavily used?

- A. Scandisk
- B. Defrag
- C. Indexing
- D. Chkdsk

Correct Answer: B

Section	1: ((no	ne)
Explan	ati	ion	

QUESTION 26

Which of the following ports is MOST likely used for high-end graphics cards?

- A. PCI
- B. PCIe
- C. ISA
- D. AGP

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 27

Which of the following Windows versions includes Windows Defender, by default? (Select TWO).

- A. Windows Vista Home Premium
- B. Windows 2000 Professional
- C. Windows XP Pro
- D. Windows XP Pro x64
- E. Windows Vista Pro

Correct Answer: AE Section: (none) Explanation

Explanation/Reference:

QUESTION 28

Which of the following commands changes a file characteristic so that it cannot be seen with a standard directory query?

- A. attrib file.txt +h
- B. attrib file.txt +r
- C. ren file.txt
- D. attrib file.txt +s

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 29

Which of the following has the HIGHEST connection latency?

- A. Satellite
- B. Cable
- C. DSL
- D. Dial-up

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 30

A technician is servicing a customer's color laser printer and notices excess toner in the printer. Which of the following tools would BEST assist the technician in removing the excess toner?

- A. Damp towel
- B. Compressed air
- C. Alcohol wipe
- D. Computer vacuum

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 31

Which of the following should be done FIRST to a hard drive before it is disposed?

- A. Partition
- B. Physical damage
- C. Data wipe
- D. Format

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 32

Which of the following would BEST provide cooling to a processor?

- A. Case fan
- B. Heatsink
- C. Liquid cooling system
- D. CPU fan

Correct Answer: C Section: (none) Explanation

QUESTION 33

A networking device that sends packets to all connections is a:

- A. gateway.
- B. hub.
- C. switch.
- D. router.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 34

Which of the following keys is pressed to enter the Windows boot options after POST?

- A. F1
- B. F8
- C. F10
- D. F12

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 35

The most important customer a technician has is:

- A. the customer standing right in front of them.
- B. the customer who owes the company the most money.
- C. the customer calling on the phone.
- D. the customer they have an appointment with in an hour.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 36

Which of the following types of printers uses a fuser to print a document?

- A. Thermal
- B. Laser
- C. Inkjet
- D. Dot Matrix

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 37

The last step in resolving an end user ticket should be which of the following?

- A. Create an incident record
- B. Verify the problem is resolved
- C. Document the solution
- D. Notify the user the problem is resolved

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 38

A military member has just returned to the United States from Europe and reports their personal desktop computer does not work. Which of the following is the MOST logical solution to this problem?

- A. The computer is unable to work in the US because of EU licensing arrangements
- B. The power supply needs to be replaced with one rated for 110 watts
- C. The power supply needs a power inverter to handle the change in cycles
- D. The power supply voltage needs to be switched to 110 from 220

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 39

Which of the following memory modules is a DDR3 chip?

- A. PC-3200
- B. PC2-4800
- C. PC2-5300
- D. PC3-8000

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 40

Which of the following utilities can be used to diagnose DirectX hardware and driver problems?

- A. Device manager
- B. Computer management
- C. msinfo32
- D. dxdiag

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 41

A user notices the department laser printer is printing light. Which of the following items should a technician do FIRST to fix this issue?

- A. Remove and clean the fuser assembly with an alcohol based cleaner.
- B. Install a maintenance kit and reset all page counts to zero.
- C. Perform a full power cycle on the printer.
- D. Clean the paper path with a damp cloth and canned air to remove any debris.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 42

Which of the following is needed to recover a system using ERD?

- A. A bootable flash drive
- B. The original installation CD/DVD
- C. An ERD partition on the hard drive
- D. An ERD for that system

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 43

A new virus is spreading via email and exploits an old vulnerability in a company's main OS. Which of the following BEST helps to mitigate this type of threat?

- A. Incident response
- B. Asset management
- C. Patch management
- D. Policies and procedures

Correct Answer: C Section: (none)

Explanation

Explanation/Reference:

QUESTION 44

Which of the following is a layer 3 device that separates broadcast domains?

- A. Network Interface Card
- B. Hub
- C. Bridge
- D. Router

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 45

There are several technicians working on various systems on a new workbench. Which of the following should be reviewed to ensure all proper procedures are followed to help reduce any possible issues?

- A. MSDS
- B. OEM
- C. ESD
- D. EMI

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 46

A technician is installing a processor upgrade onto an Intel 775 socket motherboard. Which of the following extra power connectors needs to be plugged in for the board to power on?

- A. ATX 4-pin
- B. Molex
- C. PCIe 6-pin
- D. PCle 8-pin

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 47

Several users have recently been calling the helpdesk about a recent network outage. These calls have increased in the last hour and are all by different users calling about the same issue. Which of the following types of communication skills should the helpdesk technicians MOST likely exercise while answering each call?

- A. Talk to co-workers while interacting with customers to help diagnose the issues
- B. Be culturally sensitive
- C. Provide each user with a complete, detailed report of the current outage status
- D. Listen and do not interrupt a customer and then provide a brief status update

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 48

Which of the following describes a secure connection over the Internet between two sites?

- A. FTP
- B. VLAN
- C. VPN
- D. HTTP

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 49

Which of the following helps protect important confidential information from being publicly disclosed?

- A. Hard drive wiping
- B. Social Engineering
- C. Classification
- D. RAS server

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 50

Which of the following channels, when used in close proximity to one another, provide the BEST protection against crosstalk?

- A. 1 and 11
- B. 2 and 10
- C. 6 and 1
- D. 6 and 11

Correct Answer: A Section: (none) Explanation

QUESTION 51

A technician is installing an Express Card 54 device into a laptop. How will the device MOST likely be installed?

- A. Into available expansion slot
- B. Via physical external dongle
- C. Via internal expansion slot
- D. Into any available USB slot

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 52

Which of the following devices replicates and passes data to all devices connected to it?

- A. Switch
- B. Router
- C. Bridge
- D. Hub

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 53

Incorrect menu options continue to be selected on a device. Which of the following MUST be calibrated to help correct the issue?

- A. Touchscreen
- B. Joystick
- C. Mouse
- D. On-screen keyboard

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 54

A user wants to convert their current computer into an audio/video editing workstation by upgrading components. They want to start by upgrading the hard drive. Which of the following hard drives should be chosen to maximize read/write speed?

A. Zip drive

- B. 15,000 rpm SATA
- C. 7,200 rpm IDE
- D. USB flash

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 55

A user wants to replace their 17" CRT monitor with the thinnest possible 17" monitor available. Which of the following monitors should the user purchase?

- A. LED LCD
- B. DLP
- C. CCFL LCD
- D. Plasma

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 56

Which of the following ports is used by default for IMAP traffic?

- A. 53
- B. 110
- C. 143
- D. 443

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 57

Which of the following ports is used for HTTPS traffic by default?

- A. 80
- B. 143
- C. 443
- D. 8080

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 58

Which of the following RAID types is known as only mirroring?

- A. RAID 0
- B. RAID 1
- C. RAID 5
- D. RAID 10

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 59

Which of the following network devices uses NAT to convert private IP addresses into public IP addresses?

- A. NAS
- B. Firewall
- C. Hub
- D. Bridge

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 60

Which of the following would BEST protect hardware from dust and ESD when storing it for future usage?

- A. Air filter
- B. Anti-static bags
- C. Compressed air
- D. Paper bag


Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 61

Which of the following memory types has 184 pins?

- A. DDR3
- B. DDR
- C. SDRAM
- D. DDR2



QUESTION 62

Which of the following is MOST critical when installing a new processor in an existing system?

- A. Thermal paste
- B. Fans
- C. Drive speeds
- D. Cable management

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 63

Which of the following standards or encryption types is the MOST secure for wireless networking?

- A. WEP
- B. AES
- C. TKIP
- D. DES

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 64

Which of the following cable types is used to transmit data from a satellite dish to the satellite modem?

- A. CAT5e
- B. CAT3
- C. Fiber
- D. RG-6

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 65

Which of the following cable types is rated to be run through air ducts?

A. STP

- B. Plenum
- C. PVC
- D. UTP

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 66

Which of the following is the FIRST thing a technician should do before putting their hand inside a computer case?

- A. Acquire the appropriate tools that are going to be used.
- B. Touch the case to discharge static.
- C. Remove loose jewelry.
- D. Refer to manufacturer documentation.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 67

Which of the following is the MAXIMUM theoretical transfer rate of an IDE cable?

- A. 1.54 Mbps
- B. 3.0 Gbps
- C. 133 Mbps
- D. 480 Mbps

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 68

A manager calls with an urgent issue and needs their machine fixed as soon as possible. The technician arrives and the office is empty, however there are several confidential papers on the desk. Which of the following should the technician do NEXT?

- A. Wait for the manager to return to clear the papers.
- B. Move the papers to the manager's filing cabinet.
- C. Return to the work area with another employee.
- D. Begin work on the manager's machine immediately.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 69

IEEE 1394b has a maximum transfer rate of:

- A. 400 Mbps.
- B. 480 Mbps.
- C. 800 Mbps.
- D. 1024 Mbps.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 70

A customer, who brings their laptop to work on a daily basis, calls to ask for the best way to add USB ports and an additional network card to their laptop. Which of the following would meet the user's requirements?

- A. Docking station
- B. Self powered USB hub
- C. KVM switch
- D. Non-powered USB hub

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 71

Which of the following are types of front panel connectors? (Select TWO).

- A. BNC
- B. VGA
- C. Mini-jack port
- D. PCle
- E. IEEE 1394

Correct Answer: CE Section: (none) Explanation

Explanation/Reference:

QUESTION 72

The MAXIMUM transfer rate of eSATA is:

A. 1.54 Mbps.

- B. 2.0 Gbps.
- C. 3.0 Gbps.
- D. 480 Mbps.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 73

When a power supply does not meet minimum requirements for a motherboard, which of the following can happen?

- A. Computer will not POST
- B. Computer will overheat
- C. Monitor will not power on
- D. Processor will not run at proper speed

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 74

A helpdesk technician is troubleshooting a user's monitor which has a yellow tint. The technician is informed of the asset number and discovers that it is one of the last CRT monitors. Which of the following would be the MOST appropriate response?

- A. Replace the old monitor with a new LCD.
- B. Have the user carry the monitor to the technician's desk and exchange it for an LCD monitor.
- C. Ask the user what changed recently to cause the shaking images.
- D. Tell the user to degauss the monitor.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 75

A user reports poor picture quality with a laptop connected to an LCD. Which of the following should the technician check FIRST for optimal picture quality?

- A. Native resolution
- B. Color depth
- C. Minimum brightness
- D. Maximum brightness

Correct Answer: A Section: (none)

Explanation

Explanation/Reference:

QUESTION 76

Older video cards used S-video to output to a TV. This standard has been replaced by:

- A. FireWire.
- B. SCSI.
- C. coaxial.
- D. HDMI.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 77

A user is unsatisfied with the quality of the repair that another technician has completed on their PC. Which of the following should be done to help the user?

- A. Agree with the user's complaints
- B. Clarify the user's statements
- C. Minimize the user's criticism
- D. Shadow the other technician on the next repair

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 78

A call logging process would be used by a technician in order to:

- A. assign the appropriate status level for the problem.
- B. create records which enable user authentication.
- C. help maintain a balanced workload for the help desk technicians.
- D. identify common problems among many users.

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 79

A customer asks the technician for an explanation of the cause of a printer issue, after the issue is resolved. Which of the following would be the MOST appropriate response?

A. "The process of removal is extremely complex and only certain individuals would understand".

- B. "There was a moisture build up in the paper tray that apparently caused the paper jam".
- C. "Condensation within the lower tray assembly hindered the functionality of the rollers which caused improper transfer".
- D. "The paper jam was caused because irresponsible users spilled liquid in the bottom tray".

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 80

A user has been having difficulty with their PC. Which of the following is the BEST response a technician should give when a user asks for the definition of a particular bluescreen message?

- A. "It is a message that informs the technician of what hardware needs to be replaced."
- B. "A bluescreen message is just another name for an error."
- C. "It provides the technician with more information about the problem."
- D. "It is a complex message that is very difficult to explain to those who are not familiar with computers."

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 81

Which of the following is the BEST approach a technician should take when informing a customer about their findings of any specific computer problem?

- A. Use non-technical terms.
- B. Use the appropriate acronyms.
- C. Use proper technical terms.
- D. Use email to ensure a written record.

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 82

A customer opened a ticket with the help desk two days ago to report that their computer is making a strange loud noise. Which of the following should the technician do FIRST after arriving at the site?

- A. Ask another technician who has worked with this computer previously to learn about any other prior issues.
- B. Ask the customer open-ended questions to attempt to narrow down the issue, then repeat the issue to the customer for validation.
- C. Ask the customer close-ended questions to attempt to narrow down the issue while not using technical jargon to avoid overwhelming the customer.
- D. Run preliminary diagnostic tests to narrow down the issue and update the status of the trouble ticket then ask the customer about any changes they have made to the computer.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 83

Which of the following computer types would benefit MOST from the installation of a water cooling setup?

- A. Gaming PC
- B. Home theater PC
- C. Thick client
- D. Thin client

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 84

Which of the following describes the BEST course of action when a user continuously calls a technician with computer issues instead of the helpdesk?

- A. Put all other work orders on hold and assist the user with all their computer issues.
- B. Have another technician take over support calls for this user.
- C. Explain that the user needs to fill out a work order for the computer problems.
- D. Ask the user to call another technician for more in-depth assistance.

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 85

A user has forgotten their BIOS password on their computer. Which of the following would a technician use to allow the user access to their PC?

- A. Remove the BIOS chip on the PC
- B. Re-flash the BIOS
- C. Run password cracking software on the user's PC
- D. Set the password clear jumper on the motherboard

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 86

A technician has identified prohibited content on a user's hard drive. Which of the following should be done NEXT?

- A. Warn the user
- B. Report through proper channels
- C. Wipe the drive
- D. Give the computer back to the user

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 87

Which of the following laptop hardware components requires a re-soldering process in order to replace properly?

- A. Mini PCIe wireless card
- B. Heat sink
- C. DC jack
- D. Li-Ion battery

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 88

Which of the following cable types delivers a signal over a single pin connector?

- A. Ethernet
- B. Coaxial
- C. S-video
- D. DVI

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 89

A technician installs a CD-RW drive with a feature that enables the drive to write labels directly onto the disk. The computer will burn disks but will not write labels. Which of the following should the technician do NEXT?

- A. Reboot the computer
- B. Remove the drive and reinstall
- C. Install the device driver
- D. Flash the BIOS

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 90

Before beginning hardware repair work on a PC, which of the following is the FIRST step?

- A. Install an uninterruptible power supply (UPS).
- B. Disconnect power from the PC.
- C. Ensure all Windows updates have been installed.
- D. Degauss the monitor.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 91

Which of the following is a laptop monitor technology that uses a backlight to produce an image on the screen?

- A. OLED
- B. Plasma
- C. DLP
- D. LCD

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 92

Which of the following displays has the HIGHEST Hz frequency?

- A. Plasma
- B. LED
- C. CRT
- D. LCD

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 93

A technician is installing a new power supply into a computer. One of the power supply connectors that the technician needs to connect to the motherboard is square and contains 4-pins. This connector is known as which of the following?

- A. SATA
- B. FDD
- C. IDE
- D. ATX

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 94

A customer wants to know what version of DirectX the current workstation has installed. Which of the following command line tools would the customer use?

- A. edit
- B. systeminfo
- C. gpedit.msc
- D. dxdiag

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 95

Which of the following logs contains information on overall performance and events not related to user authentication?

- A. Security
- B. Audit
- C. Application
- D. System

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 96

Which of the following connector types is used on CAT5e cable?

- A. RJ-45
- B. ST
- C. RJ-11
- D. BNC

Correct Answer: A Section: (none)

Explanation

Explanation/Reference:

QUESTION 97

Which of the following ports MUST be open to transport files across a network using FTP?

- A. 21
- B. 53
- C. 110
- D. 443

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 98

Which of the following channels should a technician choose when installing multiple wireless access points for a small office home office (SOHO) network to provide the MINIMAL interference?

- A. 1, 6,11
- B. 2, 5,10
- C. 3, 7,9
- D. 4, 5,8

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 99

Which of the following should be the FINAL step according to the troubleshooting theory?

- A. Verify full system functionality
- B. Implement preventative measures
- C. Implement the solution
- D. Document findings and outcomes

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 100

Which of the following should be completed NEXT, after testing the theory of probable cause?

A. Verify full system functionality

- B. Implement preventative measures
- C. Establish a plan of action to resolve the problem
- D. Implement the solution to the problem

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

Exam E

QUESTION 1

A technician is tasked with clearing all dust covering the fan vents of servers in a small office. Which of the following tools would be the BEST option?

- A. Small vacuum
- B. Air compressor
- C. Compressed air can
- D. Paint brush

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 2

Which of the following should a technician configure to limit access to a small office home office (SOHO) wireless network by the computer's NIC hardware identification?

- A. Encryption
- B. MAC filtering
- C. SSID broadcast
- D. DHCP

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 3

A technician is diagnosing a laser printer that is consistently having issues picking up paper from the first tray. Which of the following items would the technician replace FIRST?

- A. Toner
- B. Transfer belt
- C. Rollers
- D. Imaging drum

Correct Answer: C Section: (none) Explanation

Explanation/Reference:

QUESTION 4

A computer turns on and a "Date and Time Not Set" message appears on the screen after the manufacturer logo. Which of the following is the MOST possible cause?

A. The computer was not shut down properly.

- B. The CMOS battery needs to be replaced.
- C. The OS has stopped synching with the NTP server.
- D. The system BIOS is corrupted.

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 5

Which of the following RAID types writes data identically to multiple drives at the same time?

- A. RAID 0
- B. RAID 1
- C. RAID 5
- D. RAID 10

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 6

Which of the following devices would allow a technician to utilize a single mouse, keyboard, and display to control numerous tower PCs?

- A. EIDE
- B. MIDI
- C. SCSI
- D. KVM

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 7

A technician needs to configure a wireless small office home office (SOHO) network to provide IP addresses to devices on the network. Which of the following features should the technician configure?

- A. MAC filtering
- B. DHCP
- C. SSID broadcast
- D. Port forwarding

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 8

A technician needs to harden a wireless small office home office (SOHO) network so that internal IP addresses are hidden from Internet users. Which of the following should the technician configure?

- A. Configure NAT
- B. Configure port forwarding
- C. QoS
- D. SSID broadcast

Correct Answer: A Section: (none) Explanation

Explanation/Reference:

QUESTION 9

Which of the following protocols is used to resolve an IP address to domain name?

- A. DHCP
- B. SMB
- C. LDAP
- D. DNS

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 10

A technician needs to configure a computer system for MAXIMUM safety of stored data while staying cost effective. Which of the following RAID levels should be used?

- A. RAID 0
- B. RAID 1
- C. RAID 3
- D. RAID 5

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 11

A technician is looking to install a 3.5 inch desktop hard drive into an external enclosure. Which of the following input interfaces would provide the MOST throughput for the drive?

A. USB 2.0

- B. IEEE 1394
- C. Bi-Directional Parallel
- D. eSATA

Correct Answer: D Section: (none) Explanation

Explanation/Reference:

QUESTION 12

A consultant has been asked to install the brightest possible projector into an office conference room that has a lot of natural sunlight. Which of the following specifications would BEST meet the client's needs?

- A. Highest possible resolution
- B. High lumens
- C. High contrast
- D. HDMI 1.4 compatibility

Correct Answer: B Section: (none) Explanation

Explanation/Reference:

QUESTION 13

Which of the following types of Ethernet should be used if a technician has no choice but to run cable along fluorescent lighting arrays in a suspended ceiling?

- A. STP
- B. RG-6
- C. PVC
- D. UTP

Correct Answer: A Section: (none) Explanation

Explanation/Reference:



http://www.gratisexam.com/